

**Page Denied**

ROUTING			
TO:	NAME AND ADDRESS	DATE	INITIALS
1	Director/NPIC		
2	Room 6N106		
3			
4			
	ACTION	DIRECT REPLY	PREPARE REPLY
	APPROVAL	DISPATCH	RECOMMENDATION
	COMMENT	FILE	RETURN
	CONCURRENCE	INFORMATION	SIGNATURE
REMARKS:			
FROM: NAME, ADDRESS, AND PHONE NO.			DATE

**SECRET**


(Security Classification)


(See inside cover)

25X1  
25X1

CONTROL NO. Z- 10968/82

Copy 28

  
**Warning Notice**  
 Intelligence Sources and Methods Involved  
**NATIONAL SECURITY INFORMATION**  
 Unauthorized Disclosure Subject to Criminal Sanctions

**SECRET**

(Security Classification)

**Warning Notice**  
**Intelligence Sources and Methods Involved**  
**(WNINTEL) or (D)**

**NATIONAL SECURITY INFORMATION**  
**Unauthorized Disclosure Subject to Criminal Sanctions**

**DISSEMINATION CONTROL ABBREVIATIONS**

<b>NOFORN-</b>	Not Releasable to Foreign Nationals
<b>NOCONTRACT-</b>	Not Releasable to Contractors or Contractor/Consultants
<b>PROPIN-</b>	Caution-Proprietary Information Involved
<b>USIBONLY-</b>	USIB Departments Only
<b>ORCON-</b>	Dissemination and Extraction of Information Controlled by Originator
<b>REL . . .</b>	This Information has been Authorized for Release to . . .

SECRET

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Page 1 of 1

Attachment to Z-10568/82

Copy 28

NPIC/PEG (4/82)

AEROSPACE COMPONENT HANDLING DOLLY  
KUYBYSHEV AEROSPACE PRODUCTION PLANT 1, USSR

25X1

1. (S/D) SIGNIFICANCE: AN AEROSPACE COMPONENT HANDLING DOLLY, SIMILAR TO ONE PREVIOUSLY SEEN AT RAMENSKOYE FLIGHT TEST CENTER [REDACTED], IS OBSERVED AT KUYBYSHEV AEROSPACE PRODUCTION PLANT 1 FOR THE FIRST TIME.

25X1

2. (S/D) REMARKS: THE EMPTY DOLLY IS BENEATH THE AEROSPACE COMPONENT GANTRY CRANE, AND IS PERPENDICULAR TO THE OVERHEAD CROSSMEMBERS OF THE CRANE. THE DOLLY IS SIMILAR TO ONE WHICH HAD BEEN OBSERVED AT RAMENSKOYE, AT LEAST UNTIL [REDACTED] IT CAN NOT BE DETERMINED IF THAT DOLLY WAS AT RAMENSKOYE ON [REDACTED] THE DOLLY OBSERVED AT KUYBYSHEV ON [REDACTED] MAY OR MAY NOT BE THE SAME ONE SEEN EARLIER AT RAMENSKOYE.

25X1

25X1

25X1

(S/D) CONSTRUCTION APPEARS TO BE COMPLETE ON THE AEROSPACE COMPONENT GANTRY CRANE, AND THE PAD AREA AROUND THE CRANE HAS BEEN CLEARED OF CONSTRUCTION EQUIPMENT. AN OPENING HAS BEEN CUT IN THE FENCE NORTHEAST OF THE GANTRY, PROVIDING ACCESS TO THE KUYBYSHEV/BEZYMANKA AIRFIELD [REDACTED] GANTRY RAIL CONSTRUCTION IS CONTINUING BETWEEN THE GANTRY CRANE AND THE ASSEMBLY HALL, AND FINAL SURFACING WORK ALONG THE CENTER OF THE ACCESSWAY IS IN PROGRESS.

25X1

3. [REDACTED] COORDINATES 53-13-12N 050-18-00E

25X1

COMMENTS AND QUERIES REGARDING THIS BRIEFING BOARD MAY BE DIRECTED TO THE NPIC/PEG OPERATIONS OFFICER.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

WARNING NOTICE  
Intelligence Sources  
and Methods Involved

SECRET

25X1

**Page Denied**